

TASK (ASSUMES EQUIPMENT IS ENERGIZED AND THE WORK IS DONE WITHIN THE FLASH PROTECTION BOUNDARY)	Hazard / Risk	V Rated Gloves	V Rated Tools
Panelboards Rated 240 V and Below			
Circuit breaker (CB) or fused switch operation with covers on	0	N	N
CB or fused switch operation with covers off	0	N	N
Work on energized parts, including voltage testing	1	Y	Υ
Remove/install CB or fused switches	1	Y	Υ
Removal of bolted covers (to expose bare, energized parts)	1	N	N
Opening hinged covers (to expose bare, energized parts)	0	N	N
Panelboards or Switchboards Rated >240 V and up to 600 V and up (with molded case or insulated case circuit breakers) – Notes 1 and 3			
CB or fused switch operation with covers on	0	N	N
CB or fused switch operation with covers off	1	N	N
Work on energized parts, including voltage testing	2*	Y	Υ
600 V Class Motor Control Centers (MCCs) – Notes 2 (except as indicated) and 3			
CB or fused switch or starter operation with enclosure doors closed	0	N	N
Reading a panel meter while operating a meter switch	0	N	N
CB or fused switch or starter operation with enclosure doors open	1	N	N
Work on energized parts, including voltage testing	2*	Υ	Υ
Work on control circuits with energized parts 120 V or below, exposed	0	Υ	Υ



TASK (ASSUMES EQUIPMENT IS ENERGIZED AND THE WORK IS DONE WITHIN THE FLASH PROTECTION BOUNDARY)	Hazard / Risk	V Rated Gloves	V Rated Tools
Work on control circuits with energized parts > 120 V or below, exposed	2*	Y	Y
Insertion or removal of individual starter "buckets" from MCC – Note 4	3	Y	N
Application of safety grounds, after voltage test	2*	Y	N
Removal of bolted covers (to expose bare, energized parts)	2*	N	N
Opening hinged covers (to expose bare, energized parts)	1	N	N
600 V Class Switchgear (with power circuit breakers or fused switches) - Notes 5 and 6			
CB or fused switch operation with enclosure doors closed	0	N	N
Reading a panel meter while operating a meter switch	0	N	N
CB or fused switch operation with enclosure doors open	1	N	N
Work on energized parts, including voltage testing	2*	Y	Y
Work on control circuits with energized parts 120 V or below, exposed	0	Y	Υ
Work on control circuits with energized parts > 120 V, exposed	2*	Y	Y
Insertion or removal (racking) of CBs from cubicles, doors open	3	N	N
Insertion or removal (racking) of CBs from cubicles, doors closed	2*	N	N
Application of safety grounds, after voltage test	2*	Υ	N
Removal of bolted covers (to expose bare, energized parts)	3	N	N
Opening hinged covers (to expose bare, energized parts)	2*	N	N



TASK (ASSUMES EQUIPMENT IS ENERGIZED AND THE WORK IS DONE WITHIN THE FLASH PROTECTION BOUNDARY)	Hazard / Risk	V Rated Gloves	V Rated Tools
Other 600 V Class (277 V through 600 V, nominal) Equipment – Note 3			
Lighting or small power transformers (600 V, maximum)	-	-	-
Removal of bolted covers (to expose bare, energized parts)	2*	N	N
Opening hinged covers (to expose bare, energized parts)	1	N	N
Work on energized parts, including voltage testing	2*	Υ	Υ
Application of safety grounds, after voltage test	2*	Υ	N
Revenue meters (kW-hour, at primary voltage and current)	-	-	-
Insertion or removal	2*	Υ	N
Cable trough or tray cover removal or installation	1	N	N
Miscellaneous equipment cover removal or installation	1	N	N
Work on energized parts, including voltage testing	2*	Υ	Υ
Application of safety grounds, after voltage test	2*	Υ	N
NEMA E2 (fused contactor) Motor Starters, 2.3 kV Through 7.2 kV			
Contactor operation with enclosure doors closed	0	N	N
Reading a panel meter while operator a meter switch	0	N	N
Contactor operation with enclosure doors open	2*	N	N
Work on energized parts, including voltage testing	3	Υ	Υ
Work on control circuits with energized parts 120 V or below, exposed	0	Υ	Υ



TASK (ASSUMES EQUIPMENT IS ENERGIZED AND THE WORK IS DONE WITHIN THE FLASH PROTECTION BOUNDARY)	Hazard / Risk	V Rated Gloves	V Rated Tools
Work on control circuits with energized parts > 120 V, exposed	3	Y	Υ
Insertion or removal (racking) of starters from cubicles, doors open	3	N	N
Insertion or removal (racking) of starters from cubicles, doors closed	2	N	N
Application of safety grounds, after voltage test	3	Y	N
Removal of bolted covers (to expose bare, energized parts)	4	N	N
Opening hinged covers (to expose bare, energized parts)	3	N	N
Metal Clad Switchgear, 1kV and Above			
CB or fused switch operation with enclosure doors closed	2	N	N
Reading a panel meter while operating a meter switch	0	N	N
CB or fused switch operation with enclosure doors open	4	N	N
Work on energized parts, including voltage testing	4	Υ	Υ
Work on control circuits with energized parts 120 V or below, exposed	2	Y	Y
Work on control circuits with energized parts > 120 V, exposed	4	Y	Υ
Insertion or removal (racking) of CBs from cubicles, doors open	4	N	N
Insertion or removal (racking) of CBs from cubicles, doors closed	2	N	N
Application of safety grounds, after voltage test	4	Y	N
Removal of bolted covers (to expose bare, energized parts)	4	N	N
Opening hinged covers (to expose bare, energized parts)	3	N	N



TASK (ASSUMES EQUIPMENT IS ENERGIZED AND THE WORK IS DONE WITHIN THE FLASH PROTECTION BOUNDARY)	Hazard / Risk	V Rated Gloves	V Rated Tools
Opening voltage transformer or control power transformer compartments	4	Ν	N
Other Equipment 1kV and Above			
Metal clad load interrupter switches, fused or unfused	_	ı	_
Switch operation, doors closed	2	N	N
Work on energized parts, including voltage testing	4	Y	Υ
Removal of bolted covers (to expose bare, energized parts)	4	N	N
Opening hinged covers (to expose bare, energized parts)	3	N	Ν
Outdoor disconnect switch operation (hookstick operated)	3	Y	Y
Outdoor disconnect switch operation (gang-operated, from grade)	2	N	Ν
Insulated cable examination, in manhole or other confined space	4	Y	N
Insulated cable examination, in open area	2	Y	N

Note: V-Rated Gloves are gloves rated for the maximum line-to-line voltage upon which work will be done.

V-Rated Tools are tools and tested for the maximum line-to-line voltage upon which work will be done.

2\* means that a double layer switching hood and hearing protection are required for this task in addition to the other Hazard/Risk Category 2 requirements of SF 9005.04

Y = yes (required) and N = no (not required)